OAK RIDGE NATIONAL LABORATORY

ORNL/TM-2013/4

MANAGED BY UT-BATTELLE FOR THE DEPARTMENT OF ENERGY

High Pressure Response of Siliceous Materials

A. A. Wereszczak,* T. G. Morrissey, M. K. Ferber, K. P. Bortle, and E. A. Rodgers Ceramic Science and Technology Group Materials Science and Technology Division Oak Ridge National Laboratory Oak Ridge, TN 37831

G. Tsoi, J. M. Montgomery, and Y. K. Vohra Department of Physics University of Alabama-Birmingham Birmingham, AL 35294

> S. Toller LSP Technologies Dublin, OH 43016

* Corresponding Author: wereszczakaa@ornl.gov

Publication Date: February 2013

Prepared by the
OAK RIDGE NATIONAL LABORATORY
Oak Ridge, Tennessee 37831
managed by
UT-BATTELLE, LLC
for the
U.S. DEPARTMENT OF ENERGY
Under contract DE-AC05-00OR22725

UT-BATTELLE ORNL-27 (4-00) US ARMY TARDEC
DISTRIBUTION STATEMENT A.
Approved for public release; distribution unlimited.

Report Docume	Form Approved OMB No. 0704-0188			
Public reporting burden for the collection of information is estimate maintaining the data needed, and completing and reviewing the coll including suggestions for reducing this burden, to Washington Head VA 22202-4302. Respondents should be aware that notwithstanding does not display a currently valid OMB control number.	ection of information. Send comments regarding this burden estin lquarters Services, Directorate for Information Operations and Re	nate or any other aspect of this collection of information, ports, 1215 Jefferson Davis Highway, Suite 1204, Arlington		
1. REPORT DATE 01 FEB 2013	2. REPORT TYPE Technical Report 3. DATES COVERED 09-08-2010 to 08			
4. TITLE AND SUBTITLE High Pressure Response of Siliceous	Materials	5a. CONTRACT NUMBER DE-AC-00OR22725		
	5b. GRANT NUMBER			
	5c. PROGRAM ELEMENT NUMBER			
6. AUTHOR(S)		5d. PROJECT NUMBER		
A Wereszczak; T Morrissey; M Ferb	5e. TASK NUMBER			
		5f. WORK UNIT NUMBER		
7. PERFORMING ORGANIZATION NAME(S) AND A Materials Science and Technology Di Laboratory - Ceramic Science and Technology Area,Oak Ridge,TN,37831	8. PERFORMING ORGANIZATION REPORT NUMBER ; #23638			
9. SPONSORING/MONITORING AGENCY NAME(S) U.S. Army TARDEC, 6501 East Elev		10. SPONSOR/MONITOR'S ACRONYM(S) TARDEC		
48397-5000		11. SPONSOR/MONITOR'S REPORT NUMBER(S) #23638		
12. DISTRIBUTION/AVAILABILITY STATEMENT Approved for public release; distribution	ition unlimited			
13. SUPPLEMENTARY NOTES				
14. ABSTRACT Several siliceous (i.e., materials contamaterials were examined in this study US Army TARDEC. Some were glass	y conducted by Oak Ridge National ses (fused silica or fused quartz, Star	Laboratory and sponsored by the		

Several siliceous (i.e., materials containing, resembling, relating to or consisting of silica or silicon dioxide) materials were examined in this study conducted by Oak Ridge National Laboratory and sponsored by the US Army TARDEC. Some were glasses (fused silica or fused quartz, Starphire soda lime silicate glass, hydrated Starphire, BOROFLOAT borosilicate glass, an iron-containing soda lime silicate glass, opal (a hydrated silicate glass), ROBAX glass ceramic, and others were single crystal (α-quartz) and polycrystalline (Coesite - a high pressure phase of crystalline quartz) ceramics. Some of these materials are presently used in transparent armor systems or are under consideration for such. The testing of these materials allowed for comparisons of glass types, glass versus glass ceramics, effect of water content, and comparison of amorphous versus crystalline materials of the same composition.

15. SUBJECT TERMS								
16. SECURITY CLASSIFIC	CATION OF:		17. LIMITATION OF ABSTRACT	18. NUMBER OF PAGES	19a. NAME OF RESPONSIBLE PERSON			
a. REPORT unclassified	b. ABSTRACT unclassified	c. THIS PAGE unclassified	Public Release	72	REST ONSIDEE LEAGO.			

DOCUMENT AVAILABILITY

Reports produced after January 1, 1996, are generally available free via the U.S. Department of Energy (DOE) Information Bridge:

Web site: http://www.osti.gov/bridge

Reports produced before January 1, 1996, may be purchased by members of the public from the following source:

National Technical Information Service

5285 Port Royal Road Springfield, VA 22161

Telephone: 703-605-6000 (1-800-553-6847)

TDD: 703-487-4639 *Fax*: 703-605-6900

E-mail: info@ntis.fedworld.gov

Web site: http://www.ntis.gov/support/ordernowabout.htm

Reports are available to DOE employees, DOE contractors, Energy Technology Data Exchange (ETDE) representatives, and International Nuclear Information System (INIS) representatives from the following source:

Office of Scientific and Technical Information

P.O. Box 62

Oak Ridge, TN 37831 *Telephone:* 865-576-8401 *Fax:* 865-576-5728 *E-mail:* reports@osti.gov

Web site: http://www.osti.gov/contact.html

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States government nor any agency thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

TABLE OF CONTENTS

	Pag	e
LIST OF FIGURES	iv	r
LIST OF TABLES	viii	ĺ
EXECUTIVE SUMMARY	1	
DISCLAIMER	2	,
1. INTRODUCTION		ı
2. DESCRIPTION OF SILICEOUS TEST MATERIALS		,
3. SPHERICAL INDENTATION TESTING 3.1. Features and Advantages 3.2. Indentation Stress Field 3.3. Experimental Method 3.4. Results and Discussion		
4. DIAMOND ANVIL CELL (DAC) TESTING 4.1. Features and Advantages 4.2. DAC Stress Field 4.3. Experimental Method 4.4. Results and Discussion)
5. LASER SHOCK TESTING 5.1. Features and Advantages 5.2. Shock Stress Field 5.3. Experimental Method 5.4. Results and Discussion	32 35 36)
6. SUMMARY	48	í
REFERENCES	53	
ACKNOWLEDGMENTS	55	
APPENDIX I: List of Spherical Indentation Results	56)
APPENDIX II: List of Laser Shock Results	57	,

LIST OF FIGURES

Figure	e	Page
1.1.	Silica structure diagram after Sosman [2].	. 3
1.2.	Fused silica densification response as a function of pressure after Bridgman [4]	. 4
1.3.	Densification as a function of temperature at 3 GPa for a number of alkali silicate	
	glasses [7].	. 5
1.4.	Densification of various glasses as a function stress [10].	. 5
2.1.	Fused silica (or fused quartz) glass.	. 8
2.2.	Starphire soda lime silicate glass.	. 8
2.3.	Hydrated Starphire soda lime silicate glass (white flaked).	. 9
2.4.	BOROFLOAT borosilicate glass.	. 9
2.5.	Iron-containing soda lime silicate glass.	. 10
2.6.	Opal (hydrated amorphous silica).	. 10
2.7.	ROBAX glass ceramic.	. 11
2.8.	a-quartz single crystal ceramic.	. 11
2.9.	Coesite polycrystalline ceramic. Coesite is a high pressure phase of quartz	. 12
3.1.	Stress fields associated with spherical (Hertzian) indentation (right side of	
	schematic).	. 14
3.2.	Zwick microindentation system (left) was used for the spherical indentation.	
	Close-up of the indenter depth sensor making contact (right) with sample (indenter	
	not visible).	. 15
3.3.	Schematic of the indenter and indenter depth of penetration measurement system	. 16
3.4.	Example of a generated load-unload profile from a spherical indentation test	. 17
3.5.	Although the manufacturer reported the indenter radius to be 150 $\mu\text{m},$ two different	
	measurement methods showed the actual radius to be smaller. A radius of 110 μm	
	was used for all the stress calculations.	. 18

LIST OF FIGURES (Continued)

Figur	e	Page
3.6.	ORNL-developed software enabled the identification where apparent yielding initiated.	19
3.7.	Enlarged region of load (P) indent depth of penetration (y) where theoretical curve	
	diverges from experimental curve.	19
3.8.	A portrayal of the indenter depth of penetration to load ratio (y/P) as a function of	
	y sometimes was effective at helping the user identify the divergence.	20
3.9.	Comparison of the average apparent yield stress for all the indented siliceous	
	materials.	22
3.10.	Comparison of the calculated Hugoniot Elastic Limit from apparent yield stress	
	values with literature HEL values.	23
4.1.	Schematic of the diamond anvil cell test.	24
4.2.	Sample and ruby mounted in the diamond anvil cell.	25
4.3.	Peak ships for the ruby are used to determine stress.	25
4.4.	Stress state produced by diamond anvil cell testing.	26
4.5.	Raman spectrum as a function of stress for fused silica.	28
4.6.	Raman spectrum as a function of stress for Starphire soda lime silicate glass	28
4.7.	Raman spectrum as a function of stress for BOROFLOAT borosilicate glass	29
4.8.	Raman spectrum as a function of stress for opal (hydrated silica) glass	29
4.9.	Raman spectrum as a function of stress for hydrated Starphire soda lime silicate	
	glass.	30
4.10.	Raman spectrum as a function of stress for ROBAX glass ceramic.	30
4.11.	Raman spectrum as a function of stress for a-Quartz.	31
4.12.	Raman spectrum as a function of stress for Coesite.	31

LIST OF FIGURES (Continued)

Figure	e	Page
5.1.	Setup of laser shock system.	33
5.2.	Schematic of laser shock process.	33
5.3.	Exceeding the Hugoniot elastic limit (HEL) will deform the target material	34
5.4.	Impact pressure is a function of applied power density.	34
5.5.	Stress fields associated with uniform loading of laser shock (left side of	
	schematic).	35
5.6.	One dimensional P-wave propagation curves showing (a) compressive wave just	
	prior to reaching back surface, and the initial interaction of compressive and	
	reflected tensile waves during (b) early, (c) mid, and (d) late stages of reflection.	
	P-wave speeds were > 5500 m/s in the tested materials.	36
5.7.	Layout of laser shock tests on test tiles.	37
5.8.	Graphical example of onset of impact-side damage as a function of pressure for the	
	tin side of Starphire soda lime silicate glass. Zero represents no damage whereas a	
	value of one means damage occurred.	38
5.9.	Minimum laser shock pressure needed to initiate damage on the contact side	39
5.10.	Shock damage on fused silica glass. Shown values are the applied pressure in	
	GPa.	40
5.11.	Shock damage on the tin side of Starphire soda lime silicate glass. Shown values	
	are the applied pressure in GPa.	40
5.12.	Shock damage on the tin side of BOROFLOAT borosilicate glass. Shown values	
	are the applied pressure in GPa.	41
5.13.	Example of multiple failure initiation locations on laser shock impacted Starphire	
	soda lime silicate glass.	42
5.14.	Example of multiple failure initiation locations on laser shock impacted	
	BOROFLOAT borosilicate glass.	42

LIST OF FIGURES (Continued)

Figur	e	Page
5.15.	Side view of a surface-located damage zone caused by laser shock.	. 44
5.16.	Side view of an interior damage zone caused by laser shock.	. 45
5.17.	Minimum pressure to initiate shock damage increased with ring crack	
	initiation force measured using spherical indentation in a previous study by the	
	authors [19-21].	. 46
5.18.	Minimum pressure to initiative shock damage increased with ball impact ring	
	crack initiation force measured in a previous study by the authors [22-24]	. 46
5.19.	There was no correlation between onset of laser-shock-induced damage on the	
	impact surface and apparent yield stress.	. 47

LIST OF TABLES

Γable		Page
2.1.	Material and Test Matrix.	7
3.1.	Spherical indentation test matrix.	20
3.2.	Summary of spherical indentation results.	22
4.1.	Diamond anvil cell test matrix.	27
5.1.	Laser shock test matrix.	37
5.2.	Estimated crack propagation speeds.	43

EXECUTIVE SUMMARY

Several siliceous (i.e., materials containing, resembling, relating to or consisting of silica or silicon dioxide) materials were examined in this study conducted by Oak Ridge National Laboratory and sponsored by the US Army TARDEC. Some were glasses (fused silica or fused quartz, Starphire soda lime silicate glass, hydrated Starphire, BOROFLOAT borosilicate glass, an iron-containing soda lime silicate glass, opal (a hydrated silicate glass), ROBAX glass ceramic, and others were single crystal (α-quartz) and polycrystalline (Coesite - a high pressure phase of crystalline quartz) ceramics. Some of these materials are presently used in transparent armor systems or are under consideration for such. The testing of these materials allowed for comparisons of glass types, glass versus glass ceramics, effect of water content, and comparison of amorphous versus crystalline materials of the same composition.

The responses of these materials to high pressure loading were studied using spherical indentation testing, diamond anvil cell testing, and laser shock testing. So besides the focus of this study being on the siliceous materials, as much emphasis was placed on the efficacy of these three test methods to exploit high pressure responses. Each test is different and enables the study of different aspects of high pressure response as highlighted below.

- Spherical indentation, when using small indenter diameters, produces both high
 pressure and shear, and the loading and unloading histories enabled quantification of
 apparent yield stress and semi-quantification of energy absorption capability
 (hysteresis) of the various siliceous materials.
- 2. Diamond anvil cell testing produces a hydrostatic stress, and when concurrently used with Raman Spectroscopy, enabled the potential identification of changes of state of material as a function of quantified pressure for the various siliceous materials. Permanent densification was also detectable.
- 3. Laser shock testing produces high pressures but under dynamic conditions (impact event less than 30 ns), so this enabled the study of the effect of rate on high pressure.

 A previously unobserved damage mechanism was revealed with this testing, and the

ease or difficulty of laser-shock-induced damage initiation was deemed to be relatable to the native surface flaw population that exists on these materials.

DISCLAIMER

Reference herein to any specific commercial company, product, process, or service by trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or the Department of the Army (DoA). The opinions of the authors expressed herein do not necessarily state or reflect those of the United States Government or the DoA, and shall not be used for advertising or product endorsement purposes.

As the authors are not Government employees, this document was only reviewed for export controls, and improper Army association or emblem usage considerations. All other legal considerations are the responsibility of the authors and their employers.

1. INTRODUCTION

The ballistic impact of transparent armor materials often involve the imposition of very high pressures. Transparent armor materials are almost always silicate (siliceous) based either in the form of glass or glass ceramics, and can exist in many forms and phases if crystalline (see Fig. 1.1).




Figure 1.1. Silica structure diagram after Sosman [2].

The discussion and interpretation of high pressure response of siliceous based materials has continued for several decades now and arose from recognized pioneering work by Robert B. Sosman (regarding all things silica) and 1947 Nobel Prize recipient Percy W. Bridgman (high pressure testing). The authors of the present report do not provide a history of this discussion nor of the extensive amount of work that has occurred since then; however, the reader is directed toward selected References [1-10] should interest exist in reviewing some of the more classical literature and useful reviews.

A statement of stress or pressure units and their conversions is important when surveying the literature in context to the testing completed in this study; namely

$$1 \text{ GPa} = 1,000 \text{ MPa} = 10 \text{ kbar} \approx 10,000 \text{ kg} \cdot \text{cm}^{-2} \approx 10,000 \text{ atm}.$$
 (1)

The present study's authors use GPa for pressures generated in their testing whereas the other shown units of pressure in Eq. 1 are also often used in the literature.

Relatively large densifications of glass under pressure are known to exist with initiations occurring as low as a few GPa, as shown in Fig. 1.2, and is known to be a strong function of the glass's chemistry (Figs. 1.3-1.4). Additionally, the amount of water in a glass is known to decrease its hardness [11], therefore its role potential densification in a soda lime silicate glass is considerable too.




Figure 1.2. Fused silica densification response as a function of pressure after Bridgman [4].




Figure 1.3. Densification as a function of temperature at 3 GPa for a number of alkali silicate glasses [7].




Figure 1.4. Densification of various glasses as a function stress [10].

While pressure-induced densification is a sum of reversible and permanent densification, only recently has the latter started to have been accounted for in ballistic modeling [12]. Ballistics testing can produce densification and enable densification's study; however, it is expensive, time consuming, and not always amenable for postmortem material characterization. Consequently ballistic testing as a screening tool is impractical when there are many different potential glass candidates for transparent armor with different compositions. Therefore, three different high-pressure-application test methods were employed in this study to explore the high pressure response of siliceous materials. The methods were:

- Spherical indentation testing with small indenter diameter. Produces both high
 pressure and shear, and the loading and unloading histories enables quantification of
 apparent yield stress and semi-quantification of energy absorption capability
 (hysteresis). The authors of the present report continue to assert this method is
 applicable for characterizing high pressure response, and continue to refine its testing
 protocol and interpretation to satisfy that.
- 2. Diamond anvil cell testing. Produces a hydrostatic stress, and when concurrently used with Raman Spectroscopy, enables the potential identification of changes of state of material as a function of quantified pressure for the various siliceous materials. Permanent densification is also detectable. Most high pressure studies involve this method.
- 3. Laser shock testing. Produces high pressures but under dynamic conditions (impact event less than 30 ns), so this enables the study of the effect of rate on high pressure. This is a non-standard test; however, the authors of the present report continue to consider its utility because it (1) applies high pressure under dynamic conditions, and (2) does so in the absence of a penetrating projectile thusly enabling the potential deconvolution of shock damage and contact damage.

This study ultimately had two objectives: investigate and compare the response of various siliceous materials to high pressures, and investigate the utility and advantages and disadvantages of these three test methods to impart that high pressure.

2. DESCRIPTION OF SILICEOUS TEST MATERIALS

Several materials were evaluated but not all could be tested using all three test methods (spherical indentation, diamond anvil cell testing, and laser shock testing) owing to specimen size limitations in some cases. A summary of which materials were tested by each test method is listed in Table 2.1. Among all those listed, the responses of four materials (fused silica, Starphire soda lime silicate glass, BOROFLOAT borosilicate glass, and ROBAX glass ceramic) were evaluated by all three test techniques. The air and tin sides of the three float glasses were also tested with all three test methods. The starting material or test coupons for all the listed materials in Table 2.1 are shown in Figs. 2.1-2.9. The physical properties of these materials are disclosed later in Sections 3-5.

Table 2.1. Material and Test Matrix.

Material Class	Brand Name or Description	Manufacturer or Vendor	Spherical Indentation Testing	Diamond Anvil Cell Testing	Laser Shock Testing
	Fused silica or fused quartz	Quartz Scientific	X	X	X
	Starphire (soda lime silicate)	PPG	X Air & Tin	X Air & Tin	X Air & Tin
Glass	Hydrated Starphire	PPG (ORNL modified)		X	
Glass	BOROFLOAT (borosilicate)	SCHOTT	X Air & Tin	X	X Air & Tin
	Fe-containing soda lime silicate	Dulles Glass and Mirror	X Air & Tin		X Air & Tin
	Opal (hydrated silica)	Excalibur Mineral Corporation	X	X	
Glass Ceramic	ROBAX	SCHOTT	X	X	X
Single Crystal Ceramic	α-Quartz α-Quartz {1000} α-Quartz	Jim Coleman Crystal Mines	X	X	
Polycrystalline Ceramic	(0001) Coesite	Excalibur Mineral Corporation	A	X	



Figure 2.1. Fused silica (or fused quartz) glass.



Figure 2.2. Starphire soda lime silicate glass.




Figure 2.3. Hydrated Starphire soda lime silicate glass (white flaked).



Figure 2.4. BOROFLOAT borosilicate glass.



Figure 2.5. Iron-containing soda lime silicate glass.



Figure 2.6. Opal (hydrated amorphous silica).



Figure 2.7. ROBAX glass ceramic.



Figure 2.8. α -quartz single crystal ceramic.



Figure 2.9. Coesite polycrystalline ceramic. Coesite is a high pressure phase of quartz.

3. SPHERICAL INDENTATION TESTING

3.1. Features and Advantages

Spherical indentation using a sufficiently small diamond indenter can be a very effective way to produce a yield-like response in brittle materials with cracking (i.e., fracture) prematurely halting it. A key issue is the size of that indenter. A diameter that is too large causes sufficiently high radial tensile stresses (e.g., many hundreds of MPa) to form on the surface before a sufficiently high contact pressure develops resulting in ring and cone crack formation before yielding. This complicates the situation because once fracture starts, it is much more energetically favorable in brittle materials to promote additional crack propagation with additional load increase than to initiate a yield-like response. But a sufficiently small indenter diameter causes sufficiently high contact pressure to form first (e.g., many GPa), and the brittle material will exhibit a yield-like response first. This enables an estimation of apparent yield stress of the material. For amorphous materials, using a too-small indenter is not as problematic

as it is with polycrystalline brittle materials. In this case, one should strive to sample as many grains as possible so using too small of an indenter does not satisfy that. The authors of the present study have done many hundreds, if not thousands, of spherical indents during the last 10 years, and an indenter diameter in a range between 250-500 µm has been found to be the most versatile. It is sufficiently small to usually cause plastic-like response before fracture is induced, and its contact diameter patch during indentation is sufficiently large to sample many dozens of grains and a bulk material response.

Lastly, spherical indentation using diamond indenters can be implemented relatively inexpensively, specimen preparation can be very simple, not much material is needed, and many tests can be conducted relatively quickly to produce sufficient statistics. Spherical testing takes a quantum leap in usefulness if the indenter depth of penetration can be concurrently measured during a loading-unloading response. This feature enables repeatable data analysis and ultimate estimation of apparent yield stress.

3.2. Indentation Stress Field

The Hertzian contact stress field is well chronicled by Johnson [13] and a multitude of others, and is shown on the right hand side of Fig. 3.1. The maximum pressure in the stress field is not located at the contact surface directly under the indenter; rather, it is located at a depth below the surface of approximately one-fourth the surface contact diameter. If yielding initiates, then it initiates at that location and not at the surface.

This brings in the use of the term "apparent yield stress" in these experiments. A yield-like response is being detected in this spherical indentation by the use of a (surface located) indent depth of penetration sensor. The indenter depth of penetration sensor will not detect (permanent) penetration until the deformation field from that yield initiation finds its way to the surface. Therefore, the "actual" yielding in spherical indentation occurs at a compressive load slightly lower than what it experimentally determined here. For that reason, our reporting of a value here is not the material's actual yield stress but rather an "apparent yield stress." While it would be ideal to measure the actual yield stress (a material property), the estimation of an

apparent yield stress is a good compromise because its value indicates that the actual yield stress of a material is no larger than it. It depends on the material of course (i.e., a material's elastic modulus and Poisson's ratio and those properties of the indenter too), but the authors have performed finite element analysis in the past to try to estimate the difference between the two and the actual yield stress was $\sim 8-10\%$ less than the apparent yield stress.

In contrast to the conventional measurement of hardness, the yield stress of a material is an intrinsic material property. Hardness however is a material characteristic and *not* a material property because it depends very much on the indenter shape being used and different indenters will produce different measurements of hardness. If spherical indentation can be employed to estimate apparent yield stress, then it is a superior measurement to hardness measurement. A hardness indent can be predicted if a material's yield stress is known; however, going in the opposite direction to calculate yield stress from a hardness number is nearly impossible.




Figure 3.1. Stress fields associated with spherical (Hertzian) indentation (right side of schematic).

3.3. Experimental Method

A Zwick microhardness indenter was used to perform spherical indentation as shown in Fig. 3.2. This indenter independently measures compressive force and indenter depth of penetration during a programmed load-unload test waveform. A schematic of the indenter depth of penetration sensor is shown in Fig. 3.3. Its patented design avoids the sampling of machine compliance giving good fidelity of the measured response.






Figure 3.2. Zwick microindentation system (left) was used for the spherical indentation. Close-up of the indenter depth sensor making contact (right) with sample (indenter not visible).




Figure 3.3. Schematic of the indenter and indenter depth of penetration measurement system.

A displacement rate of 10 μ m/min was used for the loading, and a diamond indenter diameter of 220 μ m was used in all the testing. An example of representative load-unload curves for an indentation test is shown in Fig. 3.4. Acoustic emission sensing and analysis was used in all spherical indentation tests to discern where crack initiation occurred.





Figure 3.4. Example of a generated load-unload profile from a spherical indentation test.

One lesson learned is to always independently confirm the size of the employed indenter diameter. The indenter diameter was claimed to be 250 μ m by its manufacturer. However, when using that size with the to-be-described analysis, the elastic portion of the indent loading cycle could not be reconciled with theoretical prediction. The indenter's radius of curvature was then measured using two different methods (see Fig. 3.5), and its size was found to be ~ 27% smaller than what the manufacturer reported. Once this correct value of diameter was used in the Hertzian stress analysis, the measured elastic responses of the test materials behaved as expected, and this provided confident analysis for identifying and quantifying the load associated with the onset of a yield-like response.






Figure 3.5. Although the manufacturer reported the indenter radius to be 150 μm , two different measurement methods showed the actual radius to be smaller. A radius of 110 μm was used for all the stress calculations.

A computer program previously developed at ORNL was used to estimate the apparent yield stress. It compares the experimentally measured loading curve with an idealized loading curve when the material is linearly elastic. Illustrations of some of its analysis are shown in Figs. 3.6-3.8. The software identifies the load where the two curves diverge, and then this load is used in classical Hertzian theory to estimate the associated apparent yield stress.

Lastly, to employ Hertzian calculations of stresses, the elastic properties of the indented materials needed to be known first. While the above-described software, coupled with the good data generated from the Zwick indenter, allowed for determination of the material's elastic modulus, a resonant ultrasound spectroscope was instead used to independently measure elastic modulus and Poisson's ratio of the indented materials using analysis described elsewhere [14-15]. Those results are listed in Table 3.1 for all the materials that were spherically indented.




Figure 3.6. ORNL-developed software enabled the identification where apparent yielding initiated.




Figure 3.7. Enlarged region of load (P) indent depth of penetration (y) where theoretical curve diverges from experimental curve.




Figure 3.8. A portrayal of the indenter depth of penetration to load ratio (y/P) as a function of y sometimes was effective at helping the user identify the divergence.

Table 3.1. Spherical indentation test matrix.

Material Structure	Brand Name or Type	Density p (g/cm^3)	Youngs Modulus E (GPa)	Poissons Ratio V	Shear Modulus G (GPa)	Bulk Modulus K (GPa)	P-Wave or Compressive Wave Speed of Sound VL (m/s)	S-Wave or Shear Wave Speed of Sound VS (m/s)	Estimated Crack Propagation Speed VC (m/s)
Glass	Fused Silica	2.18	72.8	0.159	31.4	35.6	5957	3793	1896
Glass	Starphire - Air	2.50	73.1	0.203	30.4	41.0	5714	3488	1744
Glass	Starphire - Tin	2.50	73.1	0.203	30.4	41.0	5714	3488	1744
Glass	BOROFLOAT - Air	2.22	63.1	0.180	26.7	32.9	5560	3474	1737
Glass	BOROFLOAT - Tin	2.22	63.1	0.180	26.7	32.9	5560	3474	1737
Glass	Fe soda-lime silicate - Air	2.51	75.5	0.231	30.7	46.8	5910	3495	1748
Glass	Fe soda-lime silicate - Tin	2.51	75.5	0.231	30.7	46.8	5910	3495	1748
Glass	Opal (Hydrated silica)	1.97	75.5	0.231	30.7	46.8	6671	3945	1973
Glass Ceramic	ROBAX	2.51	99.7	0.269	39.3	71.9	7043	3959	1980
Single Crystal	a-Quartz {1000}	2.64	78	0.147	34.0	36.8	5579	3589	1794
Single Crystal	a-Quartz (0001)	2.65	100	0.047	47.8	36.8	6157	4245	2123

3.4. Results and Discussion

The results from the spherical indentation are listed in Table 3.2 for 25 N loading and a comparison of the estimated apparent yield stresses are shown in Fig. 3.9. A listing of all the indentation tests is shown in Appendix I. The BOROFLOAT's apparent yield stress (~ 5.5 GPa) was about 25% lower than that of Starphire (~ 7.5 GPa and taken here to be a reference value). The apparent yield stress of the iron-containing soda lime silicate was equivalent, that of

ROBAX was about 10% lower, and that of opal was about 80% lower than that of Starphire. Two different directions of loading were applied for alpha quartz testing due to anisotropy and the respective apparent yield stress values measured were about 15% lower than that of Starphire.

Hugoniot elastic limit (HEL_{calc}) was calculated using each materials apparent yield stress (S_{app}) and Poisson's ratio (ν) according to

$$HEL_{calc} = \left(\frac{1-\nu}{1-2\nu}\right) S_{app} \quad . \tag{2}$$

Their values are compared against literature values for three of the glasses (fused silica [16], Starphire soda lime silicate glass [17], and BOROFLOAT borosilicate glass [18]), and this is shown in Fig. 3.10. The HEL_{calc} values are somewhat larger than literature values, and this could be attributed to S_{app} being larger valued than the material's actual yield stress.

While BOROFLOAT had a lower apparent yield stress than both Starphire and the iron-containing soda lime silicate glass, its total amount of hysteresis was ~ 35 % lower when indented to the same maximum load. However, the amount of applied stress is higher in the Starphire and iron-containing soda lime silicate than the BOROFLOAT (for the same indentation force) because the elastic modulus of both of them is about 15% higher than that of BOROFLOAT. The glass ceramics had equivalent amounts of hysteresis as BOROFLOAT, but the elastic modulus of all of them is ~50% higher than that of BOROFLOAT. If the product of the amount of hysteresis and elastic modulus is related to total absorbed energy, then the glass ceramics absorb more energy than the BOROFLOAT.

Table 3.2. Summary of spherical indentation results.

Material Class	Material	Max Force (N)	Contact	Max Indent Depth of Penetration (µm)	Residual Depth (µm)	Hysteresis (N.µm)	Load at 1st Inflection (N)	Load at First Acoustic Event (N)	Estimated Load of Apparent Yielding (N)	Calculated Apparent Yield Stress (GPa)	Ring Cracking	Ring Crack Diameter (µm)	Radial Cracking
Glass	Fused Silica	25	12.53	8.8	0.13	1.8	17.91	None	15.7	7.3	Yes	61.7	No
Glass	Starphire Air	25	12.69	7.7	1.03	14.0	None	None	18.6	7.9	Yes	No data	Yes
Glass	Starphire Tin	25	12.69	8.2	1.08	14.0	15.12	None	14.9	7.0	Yes	No data	Yes
Glass	Borofloat Air	25	11.50	9.6	0.71	9.3	None	None	10.8	5.5	Yes	No data	No
Glass	Borofloat Tin	25	11.50	9.4	0.73	8.8	None	None	11.3	5.4	Yes	No data	No
Glass	Fe-SLS Air	25	10.62	8.5	0.96	13.6	None	18.3	18.0	7.6	Yes	57.5	No
Glass	Fe-SLS Tin	25	10.61	8.6	1.09	15.3	None	23.8	17.0	7.7	Yes	67.0	No
Glass	Opal (Hydrated Glass)	25	10.62	25.0	8.25	87.0	None	2.47	3.2	1.4	Yes	42.3	Yes
Glass Ceramic	ROBAX	25	12.77	8.5	0.35	7.6	11.6	11.6	12.0	6.6	Yes	65.7	No
Single Crystal	alpha Quartz (0001)	25	12.90	49.8	7.92	320.6	None	14.4	4.9	5.4	Yes	56.2	Yes
Single Crystal	alpha Quartz (1000)	25	10.61	8.5	0.39	7.7	14.19	14.55	7.2	6.1	Yes	72.1	No




Figure 3.9. Comparison of the average apparent yield stress for all the indented siliceous materials.




Figure 3.10. Comparison of the calculated Hugoniot Elastic Limit from apparent yield stress values with literature HEL values.

4. DIAMOND ANVIL CELL (DAC) TESTING

4.1. Features and Advantages

The diamond anvil cell (DAC) is a tool used to study materials experiencing high hydrostatic pressures and the phase transitions they undergo during pressure loading. It was conducted in this study in parallel to spherical indentation and laser shock testing because DAC testing is the most commonly recognized method to generate high pressure in the laboratory so it served as a reference test. A very nice review of the DAC history can be found in Ref. [19].

The DAC is able to reach very high pressure (100s of GPa) by exerting a large counter imposing force between two very small diamond facets. Rates of phase transitions, recrystallization, birefringence, and other material properties can be measured concurrently using x-ray diffraction, the ruby method, heating apparatus, and Raman and brillouin scattering.

The press consists of four main parts, a force generator, two diamond anvils, a gasket, and a pressure-transmitting medium. A schematic of the DAC is shown Fig. 4.1 and a photo of a piece of test material, ruby, and gasket is shown in Fig. 4.2.




Figure 4.1. Schematic of the diamond anvil cell test.




Figure 4.2. Siliceous material and ruby pressure sensor mounted in the diamond anvil cell. The 4:1 methanol:ethanol pressure medium is used to ensure hydrostatic pressure conditions.

The placement and co-pressurization of a ruby crystal enables the hydrostatic pressure to be measured because the peak shift as a function of pressure is calibrated for ruby. An illustration of this functionality is shown in Fig. 4.3.




Figure 4.3. Peak-shift of ruby R-1 fluorescence emission is used to measure pressure in the diamond anvil cell. The spectra are presented at a three different pressures in a typical high pressure experiment on siliceous material.

4.2. DAC Stress Field

The DAC produces a hydrostatic stress state on the test material (and the ruby). An illustration of that stress field is shown in Fig. 4.4.




Figure 4.4. Stress state produced by diamond anvil cell testing.

4.3. Experimental Method

Diamond anvil cell testing was performed on the materials listed in Table 4.1 up to approximately 20 GPa. A 4:1 methanol-ethanol mixture was used for the liquid medium and its Raman spectrum was subtracted from the generated raw spectrum of each test. A Raman spectrum was generated prior to loading, at several stresses up to 20 GPa, and then again after unloading.

Table 4.1. Diamond anvil cell test matrix.

Material Structure	Brand Name or Type	Density ρ (g/cm^3)	Youngs Modulus E (GPa)	Poissons Ratio V	Shear Modulus G (GPa)	Bulk Modulus K (GPa)	
Glass	Fused Silica	2.18	72.8	0.159	31.4	35.6	
Glass	Starphire	2.50	73.1	0.203	30.4	41.0	
Glass	BOROFLOAT	2.22	63.1	0.180	26.7	32.9	
Glass	Opal (Hydrated glass)	1.97	75.5	0.231	30.7	46.8	
Glass	Starphire - Hydrated	2.13	Unable to measure - pieces too small				
Glass Ceramic	ROBAX	2.51	99.7	0.269	39.3	71.9	
Crystal	a-Quartz	2.64	89	0.147	38.8	42.0	
Crystal	Coesite	3.0	U	Inable to measu	ire - powder fo	rm	

4.4. Results and Discussion

The Raman spectra for all the materials listed in Table 4.1 are shown in Figs. 4.5.-4.12 as a function of pressure.

All the glasses showed evidence of permanent densification when they were hydrostatically pressured up to 20 GPa. Permanent densification for the glass ceramic was not identified.

Peaks in the Raman spectrum tended to form for all the glasses and glass ceramics by 10 GPa indicating long-range ordering was being induced while under pressure. They were reversible and were absent after unloading. This suggests the material, while under pressure in a ballistic event, may have a different structure than it does under ambient temperature and pressure. Diffraction (X-Ray or neutron) analysis would need to be concurrently performed to explain what that long-range ordering was.

The amount of peak shifting per unit stress was much greater for the hydrated Starphire soda lime silicate glass than the baseline (unhydrated or as-received) Starphire. This indicates that introduced water into Starphire's amorphous structure decreases stiffness.

It appears that an additional phase is formed in pressurized Coesite sample at high pressures - perhaps Stishovite. This is evidenced by the appearance of new Raman peaks at pressures above 6.5 GPa (Fig. 4.14). Diffraction analysis and repeat testing would confirm this.




Figure 4.5. Raman spectrum as a function of stress for fused silica.




Figure 4.6. Raman spectrum as a function of stress for Starphire soda lime silicate glass.




Figure 4.7. Raman spectrum as a function of stress for BOROFLOAT borosilicate glass.




Figure 4.8. Raman spectrum as a function of stress for opal (hydrated silica) glass.




Figure 4.9. Raman spectrum as a function of stress for hydrated Starphire soda lime silicate glass.




Figure 4.10. Raman spectrum as a function of stress for ROBAX glass ceramic.




Figure 4.11. Raman spectrum as a function of stress for α -Quartz.




Figure 4.12. Raman spectrum as a function of stress for Coesite.

5. LASER SHOCK TESTING

5.1. Features and Advantages

The laser shock process is a surface modification method in which a laser is used to introduce compression in the surfaces of metallic components with minimal cold working. For this testing, its use was adapted to the testing of glass and glass ceramics. As shown in Fig. 5.1, "laser shock testing" utilizes a high powered laser to focus a short duration energy pulse onto the surface of a test coupon. A coating, which is typically black tape, is placed on the surface to facilitate the absorption of the laser beam energy. In order to direct the shock wave into surface of the work, a transparent layer, usually flowing water, is continuously applied to the surface. During a specific pulse, and as schematically shown in Fig. 5.2, the laser passes through the water and explodes the tape, creating a compressive shock wave. The energy and pressure of that shock wave peens metals (i.e., the primary use of this laser shock concept - see Fig. 5.3); however, the authors in the present study, and in past work involving polycrystalline ceramics and the study of spallation [20], sought to explore its effect on siliceous (non-metallic) materials. The peak pressure is calculated from the measured energy versus time curve as shown in Fig. 5.4. The produced energy density is high; the depth of the compressive surface stress induced by laser shock can be as much as four times deeper than that of conventional shot preening.




Figure 5.1. Setup of laser shock system.

Laser Shock Principle - Side View




Figure 5.2. Schematic of laser shock process.




Figure 5.3. Exceeding the Hugoniot elastic limit (HEL) will deform the target material.




Figure 5.4. Impact pressure is a function of applied power density.

5.2. Laser Shock Stress Field

During the laser shock process, the energy is applied very rapidly, with a rise time of approximately 4 ns, and then gradually decays over a couple tens of ns. The pressure application is nearly constant over a 5 mm diameter, and this produced "time zero" stress field is represented by the left hand side of Fig. 5.5. The resulting pressure wave mimics the behaviour shown schematically in Figure 5.6. Once this compressive wave (or P-wave) reaches the rear surface, it is reflected as a tensile wave propagating back towards the original impacted surface. During the initial stages of the reflection process, the net wave generated by the combination of the compressive and tensile waves is still primarily compressive in nature. During the mid-stage of the reflection a portion of the net wave is tensile while at the late-stage of the reflection it is predominantly tensile in nature.




Figure 5.5. Stress fields associated with uniform loading of laser shock (left side of schematic).




Figure 5.6. One dimensional P-wave propagation curves showing (a) compressive wave just prior to reaching back surface, and the initial interaction of compressive and reflected tensile waves during (b) early, (c) mid, and (d) late stages of reflection. P-wave speeds were > 5500 m/s in the tested materials.

5.3. Experimental Method

Laser shock testing was used to measure minimum pressures required to induce damage in the glasses and glass ceramics listed in Table 5.1. Each plate was attached to the end of a robotic arm as shown in Fig. 5.1. Individual shots were made in a rectangular pattern consisting of 1 to 5 positions located along 4 parallel rows (schematically shown in Fig. 5.7). The laser intensity versus time profile was measured for each shot. This information was then used to calculate the energy density assuming a laser spot diameter of 5 mm, which remained constant for all shots. The pressure was calculated from existing pressure-energy density curves. The presence of damage on the impacted surface, the back surface, or within the bulk was noted for each shot.

With the exception of the borosilicate glass, a single shot was made at each position. However, in the case of the last test for Borosilicate plate 3, multiple shots using same laser settings were made for position 4 in row 3. The laser settings were chosen such that no visible damage occurred during the first shot. Damage evolution was subsequently monitored after successive shots.

Table 5.1. Laser shock test matrix.

Material Structure	Brand Name or Type	Density ρ (g/cm^3)	Youngs Modulus E (GPa)	Poissons Ratio V	Shear Modulus G (GPa)	Bulk Modulus K (GPa)
Glass	Fused Silica	2.18	72.8	0.159	31.4	35.6
Glass	Starphire (soda-lime silicate) - Air	2.50	73.1	0.203	30.4	41.0
Glass	Starphire (soda-lime silicate) - Tin	2.50	73.1	0.203	30.4	41.0
Glass	BOROFLOAT (borosilicate) - Air	2.22	63.1	0.180	26.7	32.9
Glass	BOROFLOAT (borosilicate) - Tin	2.22	63.1	0.180	26.7	32.9
Glass	Fe-containing soda-lime silicate - Tin	2.51	75.5	0.231	30.7	46.8
Glass	Fe-containing soda-lime silicate - Air	2.51	75.5	0.231	30.7	46.8
Glass Ceramic	ROBAX	2.51	99.7	0.269	39.3	71.9




Figure 5.7. Layout of laser shock tests on test tiles.

5.4. Results and Discussion

An example of the pressure - damage initiation response is represented graphically in Fig. 5.8 for one of the materials, and the minimum pressure needed to initiate damage in all the materials is shown in Fig. 5.9. The complete listing of all measured data is included in Appendix II. Of all the materials studied, the fused silica exhibited the lowest damage initiation pressure.

Damage initiated on the tin side at lower impact stresses than the air side for the float glasses (Starphire, BOROFLOAT, and the iron-containing soda lime silicate). Additionally, more failure initiation sites were visible on the tin side than the air side for an equivalent impact pressure. This is consistent with there being a greater size and concentration of surface-located flaws on the tin side than the air side. An artifact of the damage initiation starting at lower impact pressures on the tin side is the conical and secondary cracking spreads out at shallower depths than on the air side for an equivalent impact pressure.




Figure 5.8. Graphical example of onset of impact-side damage as a function of pressure for the tin side of Starphire soda lime silicate glass. Zero represents no damage whereas a value of one means damage occurred.




Figure 5.9. Minimum laser shock pressure needed to initiate damage on the contact side.

Comparisons of laser-shock impact are shown in Figs. 5.10-5.12 for fused silica, the tin side of Starphire and the tin side of BOROFLOAT, respectively. Among the glasses, fused silica was damaged at the lowest impact stresses. Damage in Starphire tended to show a spotty, often disconnected damage zone. Damage in BOROFLOAT tended to spread out more radially at shallower depths.




Figure 5.10. Shock damage on fused silica glass. Shown values are the applied pressure in GPa.




Figure 5.11. Shock damage on the tin side of Starphire soda lime silicate glass. Shown values are the applied pressure in GPa.



Figure 5.12. Shock damage on the tin side of BOROFLOAT borosilicate glass. Shown values are the applied pressure in GPa.

Multiple failure initiation sites were visible in the impact side damage zone, and their initiations were likely a consequence of the local surface flaw population that existed in a (Hertzian) radial tensile stress annular zone around the 5 mm diameter impact area. Multiple initiation sites are quite possible owing to the short (~ 20 ns) pulse of laser shock event. Examples of this are shown in Figs. 5.13-5.14.

The formation of multiple fracture initiations is possible because the impact pulse is so short (less than 30 ns). The terminal crack propagation speed is about one-half the S-wave [21], and that speed is listed in Table 5.2 for the materials that were laser shock tested. It takes approximately 4000 ns for a crack to propagate 180° circumferentially around a 5 mm diameter, so if a pulse is shorter than that, then there is a possibility that two or more cracks could form. The pulse time was about 2 orders of magnitude shorter than that, so the observation of there being multiple failure initiations is consistent with that.




Figure 5.13. Example of multiple failure initiation locations on laser shock impacted Starphire soda lime silicate glass.




Figure 5.14. Example of multiple failure initiation locations on laser shock impacted BOROFLOAT borosilicate glass.

Table 5.2. Estimated crack propagation speeds.

Material Structure	Brand Name or Type	P-Wave or Compressive Wave Speed VL (m/s)	S-Wave or Shear Wave Speed VS (m/s)	Estimated Maximum or Terminal Crack Propagation Speed VC (m/s)	Estimated Time it takes to go around 5mm circumference (µs)	Estimated Maximum pulse time to get more than 1 initiation on 5mm circle (µs)	Estimated Maximum pulse time to get more than 1 initiation on 5mm circle (ns)
Glass	Fused Silica	5957	3793	1896	8.3	4.1	4100
Glass	Starphire (soda-lime silicate) - Air	5714	3488	1744	9.0	4.5	4500
Glass	Starphire (soda-lime silicate) - Tin	5714	3488	1744	9.0	4.5	4500
Glass	BOROFLOAT (borosilicate) - Air	5560	3474	1737	9.0	4.5	4500
Glass	BOROFLOAT (borosilicate) - Tin	5560	3474	1737	9.0	4.5	4500
Glass	Fe-containing soda-lime silicate - Tin	5910	3495	1748	9.0	4.5	4500
Glass	Fe-containing soda-lime silicate - Air	5910	3495	1748	9.0	4.5	4500
Glass Ceramic	ROBAX	7043	3959	1980	7.9	4.0	4000

A representative example of the commonly observed impact side damage zone is shown in Fig. 5.15. This impact side damage zone typically had a conical shaped habit and propagated several millimeters in from the surface.

Additionally, a subsurface damage zone sometimes formed in the (thick) Starphire and BOROFLOAT glasses whose formation was not influenced by surface-located flaws and any crack propagation associated with that impact side damage. The zone tended to form with higher impact stresses. It was not observed in the iron-containing soda lime silicate; however, that could be a consequence of that material not being tested to as high an impact stress as the Starphire and BOROFLOAT were. It was co-present with impact-initiated surface damage in almost all tests; however, failure analysis indicates this subsurface damage zone perhaps formed first, and then the crack propagation from the impact-side surface damage intersected it or was perturbed by its already-existing presence. The fact that the speed of the p-wave (compressive wave) is more than 3 times faster than the estimated terminal crack propagation speed in these materials is consistent with this interior damage zone forming first. In one test case (BOROFLOAT and 5.1 GPa), see Fig. 5.16, this subsurface damage zone formed in the absence of impact-side surface damage supporting the assertion their damage type is completely independent of impact-side surface damage. This internal damage zone was not evident in any of the laser shock tests in the glass ceramic material.




Figure 5.15. Side view of a surface-located damage zone caused by laser shock.




Figure 5.16. Side view of an interior damage zone caused by laser shock.

The impact side damage, and its ease to initiate, is most likely limited by the surface-flaw population that exists on the glasses and glass ceramics. Surface flaws are a characteristic of the material's handling history and are not necessarily characteristic of the material itself. A smaller flaw size should result in greater impact damage resistance. The trend of impact side damage initiation stress tracked (Figs 5.17-5.18) with previous work of the authors on ball impact crack initiation force and spherical indentation ring crack initiation force [22-24]; this is consistent with impact side damage initiation being associated with surface-located flaws. Impact side damage initiation stress did not track with apparent yield stress (Fig. 5.19).




Figure 5.17. Minimum pressure to initiative shock damage increased with ring crack initiation force measured using spherical indentation in previous studies by the authors [22-24].




Figure 5.18. Minimum pressure to initiative shock damage increased with ball impact ring crack initiation force measured in a previous studies by the authors [22-24].




Figure 5.19. There was no correlation between onset of laser-shock-induced damage on the impact surface and apparent yield stress.

The amount of microcracking within the 5 mm diameter impact of the ROBAX glass ceramic was more extensive (finer sized) than in the glasses. This could be a consequence of potential differences in surface flaw populations among these materials and the fact that the glass ceramic has nano crystallites in it.

If available, then a larger tile thickness of test material is desired to avoid tile fracture. A suggested thickness of 8-9 mm or greater is recommended for laser shock testing. Therefore, a fractured tile is an indicator of a "specimen size effect" and may inhibit the ability to examine bulk damage otherwise produced in a thicker tile of the same material.

6. SUMMARY

Several siliceous based materials were examined in this study. Some were glasses (fused silica or fused quartz, Starphire soda lime silicate glass, hydrated Starphire, BOROFLOAT borosilicate glass, an iron-containing soda lime silicate glass, opal (a hydrated silicate glass), a glass ceramic (ROBAX), and others were single crystal (quartz) and polycrystalline (Coesite) ceramics. Some of these materials are presently used in transparent armor systems or are under consideration for such. The testing of these materials allowed for comparisons of glass types, glass versus a glass ceramic, effect of water content, and comparison of amorphous versus crystalline materials of the same composition.

The responses of these materials to high pressure loading were studied using spherical indentation testing, diamond anvil cell testing, and laser shock testing. Each test is different and enables the study of different aspects of high pressure response. Spherical indentation, when using small indenter diameters, produces both high pressure and shear, and the loading and unloading histories enable estimations of yield stress and hysteresis. Diamond anvil cell testing produces a hydrostatic stress, and when concurrently used with Raman Spectroscopy, enables the identification of changes of state of material as a function of pressure. Laser shock testing produces high pressures but under dynamic conditions (impact event less than 30 ns), so this enables the study of the effect of rate on high pressure.

From these three tests, the following observations were made:

Spherical indentation testing

• Always confirm indenter diameter. The diameter of a commercial spherical indenter should be independently confirmed by the user because the manufacturer's reported value of it should not be trusted. For example, the diameter of the indenter used in this study was ~ 27% smaller than what the manufacturer reported, and this difference was confirmed using two different measurement methods. This is noteworthy because once a

correct value of diameter was used in the Hertzian stress analysis, the measured elastic responses of the test materials behaved as expected.

- The use of the adjective "apparent" in apparent yield stress. A yield-like response is being detected in spherical indentation by the use of a indent depth of penetration sensor. But in a Hertzian indent, when a yield-like response occurs, it occurs at a location under the indenter at a depth of approximately one-fourth the contact diameter. The indenter depth of penetration sensor will not detect (permanent) penetration until that yielding manifests itself to the surface. Therefore, the "actual" yielding in spherical indentation occurs at a compressive load slightly lower than what it experimentally determined here at an estimated, but unconfirmed, stress difference of 5-10%. For that reason, our reporting of a value here is not the material's actual yield stress but rather an "apparent yield stress."
- Estimating apparent yielding. The onset of apparent yielding (i.e., an apparent yield stress) could be estimated by (1) using an indent tester capable of concurrently measuring applied load and indenter depth of penetration, and (2) identifying the indentation load where the idealized (elastic) Hertzian loading curve diverged from the experimentally generated loading curve.
- Comparison of apparent yield stresses. The BOROFLOAT's apparent yield stress (~ 5.5 GPa) was about 25% lower than that of Starphire (~ 7.5 GPa). The apparent yield stress of the iron-containing soda lime silicate was equivalent to that of the Starphire. The apparent yield stress of ROBAX was about 10% lower. The apparent yield stress of opal was about 80% lower than that of Starphire. Two different directions of loading on alpha quartz had anisotropy and their apparent yield stresses were about 15% lower than that of Starphire.
- Hardness, spherical indentation, yield stress, and material properties. Estimating the yield stress (or an apparent yield stress) of a material is determining an intrinsic material property. Hardness, on the other hand, is not a material property but rather is a material

characteristic because it depends on the indenter shape being used. If spherical indentation can be employed to estimate apparent yield stress, then it is a superior measurement.

• Hysteresis and elastic modulus. While BOROFLOAT had a lower apparent yield stress than both Starphire and the iron-containing soda lime silicate glass, its total amount of hysteresis was ~ 35 % lower when indented to the same maximum load. However, the amount of applied stress is higher in the Starphire and iron-containing soda lime silicate than the BOROFLOAT (for the same indentation force) because the elastic modulus of both of them is about 15% higher than that of BOROFLOAT. The glass ceramic had an equivalent amount of hysteresis as BOROFLOAT, but its elastic modulus is ~50% higher than that of BOROFLOAT. If the product of the amount of hysteresis and elastic modulus is related to total absorbed energy, then the glass ceramic absorbs more energy than the BOROFLOAT.

Diamond anvil cell testing

- *Permanent densification*. All the glasses showed evidence of permanent densification when they were hydrostatically pressured up to 20 GPa. The identification of permanent densification for the glass ceramics could not be made.
- Long-range ordering. While under pressure, peaks in the Raman spectrum tended to form for all the glasses and glass ceramics by 10 GPa indicating long-range ordering. They were reversible and were absent after unloading. Diffraction (X-Ray or neutron) analysis would need to be concurrently performed to explain what that long-range ordering was.
- Effect of water in glass. The amount of peak shifting per unit stress was much greater for the hydrated Starphire soda lime silicate glass than the baseline (unhydrated or asreceived) Starphire. This indicates that introduced water into Starphire's amorphous structure decreases stiffness.

Coesite and Stishovite. It appears that an additional phase is formed in pressurized
 Coesite sample at high pressures - perhaps Stishovite. This is evidenced by the
 appearance of new Raman peaks at pressures above 6.5 GPa. Diffraction analysis and
 repeat testing would confirm this.

Laser shock testing

- Surface flaws. The impact side damage, and its ease to initiate, is most likely limited by the surface-flaw population that exists on the glasses and glass ceramics. Surface flaws are a characteristic of the material's handling history and not necessarily characteristic of the material itself. A smaller flaw size should result in greater impact damage resistance. Impact side damage initiation stress tracked with previous work of the authors on ball impact crack initiation force and spherical indentation ring crack initiation force; this is consistent with impact side damage initiation being associated with surface-located flaws. Impact side damage initiation stress did not track with apparent yield stress.
- Multiple failure initiations. Multiple failure initiation sites were visible in the impact side damage zone, and their initiations were likely a consequence of the local surface flaw population that existed in a (Hertzian) radial tensile stress annular zone around the 5 mm diameter impact area. Multiple initiation sites are quite possible owing to the short (~ 20 ns) pulse of laser shock event.
- Tin side damages easier in float glass. Damage initiated on the tin side at lower impact stresses than the air side for the float glasses (Starphire, BOROFLOAT, and the iron-containing soda lime silicate). Additionally, more failure initiation sites were visible on the tin side than the air side for an equivalent impact pressure. This is consistent with there being a greater size and concentration of surface-located flaws on the tin side than the air side. An artifact of the damage initiation starting at lower impact pressures on the tin side is the conical and secondary cracking spreads out at shallow depths than on the air side for an equivalent impact pressure.

- Glass ceramic damaged differently. The amount of microcracking within the 5 mm diameter impact of the ROBAX glass ceramic was more extensive (finer sized) than the glasses. This could be a consequence of potential differences in surface flaw populations among between them.
- Interior damage zone. A subsurface damage zone sometimes formed in the (thick) Starphire and BOROFLOAT glasses whose formation was not influenced by surfacelocated flaws and any crack propagation associated with that impact side damage. The interior damage zone tended to form with higher impact stresses. It was not observed in the iron-containing soda lime silicate; however, that could be a consequence of that material not being tested to as high an impact stress as the Starphire and BOROFLOAT were. The interior damage zone was co-present with impact-initiated surface damage in almost all tests; however, failure analysis indicates this subsurface damage zone perhaps formed first, and then the crack propagation from the impact-side surface damage intersected it or was perturbed by its already-existing presence. The fact that the speed of the p-wave (compressive wave) is more than 3 times faster than the estimated terminal crack propagation speed in these materials is consistent with this interior damage zone forming first. In one test case (BOROFLOAT and 5. 1 GPa), this subsurface damage zone formed in the absence of impact-side surface damage supporting the assertion the damage type is completely independent of impact-side surface damage. This internal damage zone was not evident in any of the laser shock tests in the glass ceramic material.
- Minimum tile thickness. If available, then a larger tile thickness of a test material is
 desired to avoid tile fracture. A suggested thickness of 8-9 mm or greater is
 recommended for laser shock testing. A fractured tile is a "specimen size effect" and
 may inhibit the ability to examine bulk damage that may otherwise be observed in a
 thicker tile of the same material.

REFERENCES

- [1] R. B. Sosman, *The Phases of Silica*, Rutgers University Press, New Brunswick, NJ, 1965.
- [2] R. B. Sosman, "New and Old Phases of Silica," *Transactions of the British Ceramic Society*," 54:655-670 (1977).
- [3] P. W. Bridgman, "The Compression of 39 Substances to 100,000 kg/cm²," *Proceedings of the American Academy of Arts and Sciences*, 76:55-70 (1948).
- [4] P. W. Bridgman and I. Simon, "Effects of Very High Pressure on Glass," *Journal of Applied Physics*, 24:405-413 (1953).
- [5] R. Roy and H. M. Cohen, "Effects of High Pressure on Glass: a Possible Piezometer for the 100-Kilobar Region," *Nature*, 190:798-799 (1961).
- [6] S. Sakka and J. D. Mackenzie, "High Pressure Effects on Glass," *Journal of Non-Crystalline Solids*, 1:107-142 (1969).
- [7] D. R. Uhlmann, "Densification of Alkali Silicate Glasses at High Pressure," *Journal of Non-Crystalline Solids*, 13:89-99 (1973/74).
- [8] R. B. Heimann, "High-Temperature and High-Pressure Polymorphs of Silica: A Review," *Materials Science and Engineering*, 9:57-67 (1977).
- [9] S. Susman, K. J. Volin, D. L. Price, M. Grimsditch, J. P. Rino, R. K. Kalia, P. Vashishta, G. Gwanmesia, Y. Wang, and R. C. Liebermann, "Intermediate-range order in permanently densified vitreous SiO2: a neutron-diffraction and molecular-dynamics study," *Physical Review B*, 43:1194-97 (1991).
- [10] T. Rouxel, H. Ji, T. Hammouda, and A. Moreac, "Poisson's Ratio and the Densification of Glass under High Pressure," *Physical Review Letters*, 100:225501 (2008).
- [11] M. Takata, M. Tomozawa, and E. B. Watson, "Effect of Water Content on Mechanical Properties of Na₂O-SiO₂ Glasses, *Journal of the American Ceramic Society*, 65:C156-C157 (1982).
- [12] T. J. Holmquist and G. R. Johnson, "Model for Glass Subjected to Large Strains, High Strain Rates, and High Pressures," *Journal of Applied Mechanics*, 78:051003 (2011).
- [13] K. L. Johnson, *Contact Mechanics*, Cambridge University Press, Cambridge, 1985.

- [14] A. A. Wereszczak, R. H. Kraft, and J. J. Swab, "Flexural and Torsional Resonances of Ceramic Tiles via Impulse Excitation of Vibration," *Ceramic Engineering and Science Proceedings*, 24:207-13 (2003).
- [15] A. A. Wereszczak, "Elastic Property Determination of WC Spheres and Estimation of Compressive Loads and Impact Velocities That Initiate Their Yielding and Cracking," *Ceramic Engineering and Science Proceedings*, [7], 27:211-223 (2006).
- [16] L. M. Barker and R. E. Hollenbach, "Shock-Wave Studies of PMMA, Fused Silica, and Sapphire," *Journal of Applied Physics*, 41:4208-4226 (1970).
- [17] C. S. Alexander, L. C. Chhabildas, W. D. Reinhart, and D. W. Templeton, "Changes to the Shock Response of Fused Quartz Due to Glass Modification," *International Journal of Impact Engineering*, 35:1376-1385 (2008).
- [18] N. Bourne, J. Millett, Z. Rosenberg, and N. Murray, "On the Shock Induced Failure of Brittle Solids," *Journal of the Mechanics and Physics of Solids*, 46:1887-1908 (1998).
- [19] W. A. Bassett, "Diamond Anvil Cell, 50th Birthday," *High Pressure Research*, 29:163-186 (2009).
- [20] T. J. Holmquist and A. A. Wereszczak, "Laser Induced Spall in Silicon Carbide," 23rd International Symposium on Ballistics, Tarragona, Spain, 16-20 April, 2007.
- [21] G. D. Quinn, "Fractography of Ceramics and Glasses," NIST Special Publication 960-16, 2006, US Government Printing Office, Washington, DC.
- [22] A. A. Wereszczak, E. E. Fox, T. G. Morrissey, and D. J. Vuono, "Low Velocity Sphere Impact of a Soda Lime Silicate Glass," ORNL/TM-2011/259, October, 2011.
- [23] T. G. Morrissey, M. K. Ferber, A. A. Wereszczak, and E. E. Fox, "Low Velocity Sphere Impact of a Borosilicate Glass," ORNL/TM-2012/60, May 2012.
- [24] A. A. Wereszczak, E. E. Fox, T. G. Morrissey, and D. J. Vuono, "Initial Examination of Low Velocity Sphere Impact of Glass Ceramics," ORNL/TM-2012/139, June, 2012.

ACKNOWLEDGEMENTS

Research performed under Work For Others funded by U.S. Army Tank-Automotive Research, Development and Engineering Center, under contract DE-AC-00OR22725 with UT-Battelle, LLC.

The authors express sincere appreciation to A. Dolan of the U.S. Army Research, Development and Engineering Command - Tank-Automotive and Armaments Command for sponsoring this work, ORNL's J. Hemrick and R. Wiles for their review of this report and T. Holmquist for their helpful comments.

This submission was produced by a contractor of the United States Government under contract DE-AC05-00OR22725 with the United States Department of Energy. The United States Government retains, and the publisher, by accepting this submission for publication, acknowledges that the United States Government retains, a nonexclusive, paid-up, irrevocable, worldwide license to publish or reproduce the published form of this submission, or allow others to do so, for United States Government purposes.


APPENDIX I: List of Spherical Indentation Results

Date	Material	Series #	Indenter Diameter (μm)	Max Force (N)	Max Hertz Stress (Mpa)	Max IDOP (µm)	Residual Depth (μm)	Histeresis (N.μm)	1st Point of Inflection (N)	First Acoustic Event Load (N)	Theritcal Shift outside of Experimental noise (N)	Clalculated Yield Stress (Mpa)	Ring Cracking
11-Jun-12		1	110	25.00	11503	8.2	0.6	9.8		No Accoustic Data	7.5	5.2	yes
11-Jun-12	Borofloat Thin Air	2	110	5.01	6732	1.2	0.0	-0.1	No Inflection	No Accoustic Data	Used to Calc E	N/A	no
11-Jun-12	Borofloat Thin Air	3	110	25.00	11503	8.2	0.6	9.9	No Inflection	No Accoustic Data	7.5	5.2	yes
12-Jun-12	Borofloat Thin Air	5	110	13.01	9253	6.2	0.2	1.4		No Accoustic Data	4.0	4.2	yes
11-Jun-12		4	110	25.00	11503	10.0	0.9	9.5	12.3	No Accoustic Data	5.0	4.5	yes
11-Jun-12		6	110	5.01	6732	3.2	0.2	0.1	No Inflection	No Accoustic Data	3.0	3.8	no
11-Jun-12	Borofloat Thin Air	7	110	25.02	11506	10.2	0.9	9.1	7.5	No Accoustic Data	5.0	4.5	yes
11-Jun-12	Borofloat Thin Tin	1	110	25.01	11505	7.9	0.8	9.4	15.6	No Accoustic Data	10.5	5.3	yes
	Borofloat Thin Tin	2	110	4.99	6723	3.4	0.2	0.2	No Inflection	No Accoustic Data	Used to Calc E	N/A	no
	Borofloat Thin Tin	3	110	25.01	11505	9.8	0.8	9.9	No Inflection	No Accoustic Data	6.0	4.4	yes
11-Jun-12	Borofloat Thin Tin	4	110	12.99	9248	6.3	0.3	1.6	No Inflection	No Accoustic Data	4.0	3.9	yes
11-Jun-12	Borofloat Thin Tin	5	110	25.00	11503	9.7	0.9	10.0	No Inflection	No Accoustic Data	3.0	3.5	yes
	Borofloat BS 3x3 Air	1	110	25.03	11507	10.0	0.7	9.2	15.4	15.7	20.0	7.3	yes
	Borofloat BS 3x3 Air	2	110	5.00	6727	3.2	0.2	-0.2	No Inflection	None	Used to Calc E	N/A	no
	Borofloat BS 3x3 Air	3	110	25.01	11505	10.0	0.7	9.3	No Inflection	9.8	13.0	6.3	yes
	Borofloat BS 3x3 Air	4	110	13.00	9250	6.4	0.5	1.2	No Inflection	12.1	None	N/A	yes
	Borofloat BS 3x3 Air	5	110	25.01	11505	9.8	0.7	8.6	12.3	12.4	7.0	5.1	yes
	Borofloat BS 3x3 Tin	1	110	25.00	11503	9.3	0.6	7.5	No Inflection	23.8	16.0	6.6	yes
	Borofloat BS 3x3 Tin	2	110	5.00	6727	3.1	0.1	0.0	No Inflection	None	Used to Calc E	N/A	no
	Borofloat BS 3x3 Tin	3	110	25.01	11505	9.6	0.7	6.3	No Inflection	8.6	15.0	6.4	yes
	Borofloat BS 3x3 Tin	4	110	13.02	9255	5.9	0.1	0.6	No Inflection	None	12.5	6.1	no
	Borofloat BS 3x3 Tin	5	110	25.01	11505	10.0	0.6	9.7	13.8	7.8	17.0	6.7	yes
8-Jun-12	Starphire 2x2 Air	1	110 110	25.01 5.01	12691 7426	8.2 2.0	1.1 0.1	14.7 -0.1	17.5	No Accoustic Data	17.5	7.7 N/A	yes
8-Jun-12	Starphire 2x2 Air	2							No Inflection	No Accoustic Data	Used to Calc E		no
8-Jun-12	Starphire 2x2 Air	3	110	25.07	12701	7.4	1.2	16.2	No Inflection	No Accoustic Data	16.5	7.6	yes
8-Jun-12	Starphire 2x2 Air	4	110	13.03	10212	3.6	0.2	0.8	No Inflection	No Accoustic Data	None	N/A	yes
8-Jun-12	Starphire 2x2 Air	5	110	25.02	12693	5.7	0.9	12.2	No Inflection 7.2	No Accoustic Data	17.0	7.7	yes
7-Jun-12	Starphire 2x2 Tin	1	110	25.01	12691	8.6	1.3	18.7		No Accoustic Data	8.0	6.0	yes
7-Jun-12	Starphire 2x2 Tin	2	110	5.05	7445	1.0	0.0	0.1	No Inflection	No Accoustic Data	Used to Calc E	N/A	no
7-Jun-12	Starphire 2x2 Tin	3	110	25.01	12691	8.1	1.2	18.2	22.0	No Accoustic Data	15.0	7.3	yes
7-Jun-12	Starphire 2x2 Tin	4	110	13.01	10207	4.0	0.2	1.2	No Inflection	No Accoustic Data	13.0	7.0	no
7-Jun-12	Starphire 2x2 Tin	5	110	25.00	12689	7.6	1.0	12.4	16.2	No Accoustic Data	15.0	7.3	yes
26-Jun-12	Starphire 3x3 Air	1	110	25.00	12689	7.8	1.1	15.4	No Inflection	17.0	21.0	8.2	yes
26-Jun-12	Starphire 3x3 Air	2	110	5.03	7436	2.7	0.2	0.1	No Inflection	None	Used to Calc E	N/A 7.8	no
26-Jun-12	Starphire 3x3 Air	3	110	25.04	12696	8.6	1.1	12.7	No Inflection	22.4	18.0		yes
26-Jun-12	Starphire 3x3 Air	4	110	13.04	10215	5.3	0.3	1.2	No Inflection	None	None	N/A	no
26-Jun-12	Starphire 3x3 Air	5	110	25.00	12689	8.4	0.9	12.4	No Inflection	21.7	22.0	8.3	yes
21-Jun-12	Starphire 3x3 Tin	1	110	25.01	12691	8.2	0.9	11.0	No Inflection	1.8	11.0	6.9	yes
21-Jun-12	Starphire 3x3 Tin	2	110	5.01 25.01	7426	2.7	0.1	-0.1	No Inflection	None	Used to Calc E	N/A 7.3	no
21-Jun-12	Starphire 3x3 Tin	3	110		12691		1.1	11.7	No Inflection	24.37 (unlaoding) None	13.0 8.5		yes
21-Jun-12	Starphire 3x3 Tin	_	110 110	13.03	10212	5.3	0.3	1.2	No Inflection	None 21.8		6.3	no
21-Jun-12	Starphire 3x3 Tin Fe SLS Glass Air	5	110	25.01 25.03	12691 10618	8.3 8.8	1.0	11.7	No Inflection 17.8	13.3	13.5	7.3	yes
	Fe SLS Glass Air	2	110	5.01	6211	2.6	0.1	0.1	No Inflection	None	Used to Calc E	N/A	yes no
	Fe SLS Glass Air	3	110	25.00	10614	8.4	0.9	11.9	No Inflection	23.3	19.5	7.9	ves
	Fe SLS Glass Air	4	110	13.00	8535	5.2	0.1	1.2	No Inflection	None	None	N/A	no
	Fe SLS Glass Air	5	110	25.01	10615	8.4	0.9	10.8	No Inflection	None Recorded	20.0	8.0	no
	Fe SLS Glass Tin	1	110	24.99	10612	8.6	1.1	15.6	No Inflection	23.2	17.0	7.6	yes
	Fe SLS Glass Tin	2	110	5.00	6207	2.9	0.2	0.1	No Inflection	None	Used to Calc E	N/A	no
	Fe SLS Glass Tin	3	110	25.03	10618	8.5	1.0	15.2	No Inflection	23.5	16.0	7.4	yes
	Fe SLS Glass Tin	4	110	13.00	8535	5.3	0.3	1.0	No Inflection	None	None None	N/A	no
	Fe SLS Glass Tin	5	110	25.00	10614	8.6	1.1	14.9	No Inflection	24.8	18.0	7.7	yes
12-Jul-12	ROBAX GC	1	110	25.04	12769	8.5	0.4	9.0	9.5	9.9	10.0	6.2	yes
12-Jul-12	ROBAX GC	2	110	5.01	7468	2.7	0.1	0.0	No Inflection	2.7	Used to Calc E	N/A	no
12-Jul-12	ROBAX GC	3	110	25.02	12765	8.3	0.3	6.4	15.2	15.1	14.0	6.9	yes
12-Jul-12	ROBAX GC	4	110	13.00	10262	5.1	0.1	1.8	No Inflection	10.2	11.5	6.5	yes
12-Jul-12	ROBAX GC	5	110	25.02	12765	8.6	0.3	7.3	10.1	9.7	12.0	6.6	yes
	Crystal Quartz (0001)	1	110	24.97	12902	32.7	0.7	223.3	No Inflection	15.3	9.4	8.0	yes
	Crystal Quartz (0001)	2	110	5.04	7570	2.4	0.0	0.1	No Inflection	3.7	5.0	6.5	no
	Crystal Quartz (0001)	3	110	24.97	12902.36	52.7	0.8	380.8	No Inflection	18.6	3.5	5.7	yes
	Crystal Quartz (0001)	4	110	12.98	10374	35.2	2.2	151.5	No Inflection	10.7	2.0	4.8	yes
	Crystal Quartz (0001)	5	110	25.01	12909	63.9	22.2	357.6	No Inflection	9.4	1.8	4.6	yes
	Crystal Quartz (1000)	1	110	25.04	10616	9.4	0.6	12.3	8.7	8.7	3.5	4.4	yes
12-Oct-12	Crystal Quartz (1000)	2	110	5.00	6206	2.9	0.1	0.5	No Inflection	2.8	Used to Calc E	N/A	no
	Crystal Quartz (1000)	3	110	25.01	10612	8.3	0.3	6.6	20.0	20.2	12.0	6.6	yes
	Crystal Quartz (1000)	4	110	13.02	8537	5.5	0.3	2.8	8.7	9.0	3.0	4.2	no
	Crystal Quartz (1000)	5	110	25.01	10613	7.8	0.2	4.1	13.8	14.8	6.0	5.2	yes
7-Jun-12	Fused Silica	1	110	25.00	12530	9.0	0.1	1.3	19.6	No Accoustic Data	11.0	6.6	yes
7-Jun-12	Fused Silica	2	110	4.99	7322	3.0	0.1	-0.1		No Accoustic Data	Used to Calc E	N/A	no
7-Jun-12	Fused Silica	3	110	25.00	12530	8.7	0.2	1.7	13.1	No Accoustic Data	14.0	7.1	yes
7-Jun-12	Fused Silica	4	110	13.05	10089	5.6	0.0	0.3	No Inflection	No Accoustic Data	11.5	6.7	yes
7-Jun-12	Fused Silica	5	110	25.00	12530	8.6	0.1	2.3	21.0	No Accoustic Data	22.0	8.3	yes
12-Oct-12	Opal	1	110	25.02	10616	32.1	14.2	120.1	No Inflection	3.1	1.0	1.0	Yes
12-Oct-12	Opal	2	110	5.01	6211	8.0	2.1	4.8	No Inflection	2.1	Used to Calc E	N/A	Yes
12-Oct-12	Opal	3	110	25.00	10614	21.9	6.1	71.7	No Inflection	2.0	6.0	1.8	Yes
		4	110	12.99	8533	14.9	3.4	24.0	No Inflection	3.6	5.5	1.7	Yes
	Opal												
12-Oct-12 12-Oct-12	Opal Opal	5	110	5.00	6207	6.3	0.4	1.7	No Inflection	None Recorded	Used to Calc E	N/A	Yes

APPENDIX II: List of Laser Shock Results


Fused Silica or Fused Quartz Glass

										Visible	Visible	
					Energy	Pulse Width	Spot Diameter	Power Density	Pressure	Contact Side	Spall or Back Side	Comments
Row	Sample No	Material	ORNL ID	Shot#	(1)	(ns)	(mm)	GW/cm^2	GPa	Damage?	Damage?	
1	212 304-1	Fused Silica	6x6x0.25" thk	1	20.1	25.4	5.0	4.030	5.094	Y	Υ	
1	212 304-1	Fused Silica	6x6x0.25" thk	2	20.2	20.4	5.0	5.043	5.736	Y	Υ	
1	212 304-1	Fused Silica	6x6x0.25" thk	3	19.9	20.5	5.0	4.944	5.676	Υ	Υ	
1	212 304-1	Fused Silica	6x6x0.25" thk	4	20.1	20.0	5.0	5.118	5.781	Υ	Υ	
1	212 304-1	Fused Silica	6x6x0.25" thk	5	20.2	19.6	5.0	5.249	5.859	Y	Υ	
1	212 304-1	Fused Silica	6x6x0.25" thk	6	20.6	20.0	5.0	5.246	5.857	Y	Υ	
1	212 304-2	Fused Silica	6x6x0.25" thk	1	5.2	21.6	5.0	1.226	2.713	Υ	Υ	
1	212 304-2	Fused Silica	6x6x0.25" thk	2	4.1	22.0	5.0	0.949	2.369	Y	N	
1	212 304-2	Fused Silica	6x6x0.25" thk	3	3.2	20.4	5.0	0.794	2.155	Y	Υ	
1	212 304-2	Fused Silica	6x6x0.25" thk	4	2.7	22.8	5.0	0.596	1.853	Y	N	
1	212 304-2	Fused Silica	6x6x0.25" thk	5	1.4	21.6	5.0	0.323	1.339	Y (vs)	N	
2	212 304-2	Fused Silica	6x6x0.25" thk	1	1.3	22.4	5.0	0.286	1.257	Y (vs)	N	
2	212 304-2	Fused Silica	6x6x0.25" thk	2	1.3	22.8	5.0	0.284	1.250	Y (vs)	N	
2	212 304-2	Fused Silica	6x6x0.25" thk	3	2.6	21.2	5.0	0.629	1.906	Y	Y	
2	212 304-2	Fused Silica	6x6x0.25" thk	4	2.7	22.4	5.0	0.612	1.877	Y	Y	
1	212 304-3	Fused Silica	6x6x0.25" thk	1	3.5	21.6	5.0	0.825	2.200	Y	Υ	
1	212 304-3	Fused Silica	6x6x0.25" thk	2	0.9	22.4	5.0	0.205	1.052	N	N	
1	212 304-3	Fused Silica	6x6x0.25" thk	3	0.9	22.8	5.0	0.201	1.042	N	N	
1	212 304-3	Fused Silica	6x6x0.25" thk	4	1.3	19.6	5.0	0.330	1.354	N	N	
3	212 304-3	Fused Silica	6x6x0.25" thk	1	1.2	20.4	5.0	0.287	1.258	N	N	
3	212 304-3	Fused Silica	6x6x0.25" thk	2	2.0	21.6	5.0	0.460	1.614	Y	Υ	
3	212 304-3	Fused Silica	6x6x0.25" thk	3	1.9	21.6	5.0	0.446	1.588	Y	Υ	
3	212 304-3	Fused Silica	6x6x0.25" thk	4	1.6	22.0	5.0	0.359	1.416	N	Υ	Possible internal defect




Starphire Soda Lime Silicate Glass Air Side

											Visible	Visible	
						Energy	Pulse Width	pot Diamet	Power Density	Pressure	Contact Side	Spall or Back Side	Comments
	Row	Sample No	Material	ORNL ID	Shot #	(J)	(ns)	(mm)	GW/cm^2	GPa	Damage?	Damage?	
•	1	2-Air side	Starphire	6by6by 3/4 thk	1	5.0	22.8	5.0	1.117	2.582	N	N	
	1	2-Air side	Starphire	6by6by 3/4 thk	2	8.0	22.8	5.0	1.778	3.303	N	N	
	1	2-Air side	Starphire	6by6by 3/4 thk	3	13.5	22.8	5.0	3.016	4.369	N	N	
	1	2-Air side	Starphire	6by6by 3/4 thk	4	17.3	20.8	5.0	4.236	5.230	l N	N	
	1	2-Air side	Starphire	6by6by 3/4 thk	5	21.5	20.8	5.0	5.264	5.868	Y	N	Corner edge damage; grew with time
	2	2-Air side	Starphire	6by6by 3/4 thk	1	23.5	19.2	5.0	6.234	6.417	Y	N	
	2	2-Air side	Starphire	6by6by 3/4 thk	2	31.7	19.6	5.0	8.237	7.437	Ý	N	
	2	2-Air side	Starphire	6by6by 3/4 thk	3	34.4	18.0	5.0	9.733	8.124	N N	N	
	2	2-Air side	Starphire	6by6by 3/4 thk	4	34.1	16.4	5.0	10.590	8.495	Y	Y	
	-	2711 0100	Ottarprino	objoby or and	4	34.1	10.4	3.0	10.550	0.455	· '		
	3	2-Air side	Starphire	6by6by 3/4 thk	0	33.6	19.2	5.0	8.913	7.754	Y	N	Multiple damage pockets outside of impact Multiple damage pockets outside of impact; damage on back surface way out of
	3	2-Air side	Starphire	6by6by 3/4 thk	1	34.2	18.8	5.0	9.265	7.915	Y	Υ	pulse zone
											,		
	1	3-Air side	Starphire	6by6by 3/4 thk	1	13.5	21.2	5.0	3.243	4.540	vs	N	
	1	3-Air side	Starphire	6by6by 3/4 thk	2	16.2	21.6	5.0	3.820	4.951	N	N	
	1	3-Air side	Starphire	6by6by 3/4 thk	3	18.7	21.2	5.0	4.492	5.395	N	N	
	1	3-Air side	Starphire	6by6by 3/4 thk	4	19.6	20.0	5.0	4.991	5.704	Y	Y	
]		
	3	3-Air side	Starphire	6by6by 3/4 thk	1	21.5	20.0	5.0	5.475	5.991	Y multiple	N	
	3	3-Air side	Starphire	6by6by 3/4 thk	2	22.4	19.6	5.0	5.821	6.188	Y multiple	N	
	3	3-Air side	Starphire	6by6by 3/4 thk	3	23.8	19.6	5.0	6.184	6.390	Y multiple	N	
	3	3-Air side	Starphire	6by6by 3/4 thk	4	30.7	18.8	5.0	8.317	7.475	Y multiple	N	




Starphire Soda Lime Silicate Glass Tin Side

										Visible	Visible
					Energy	Pulse Width	pot Diamete	ower Densit	Pressure	Contact Side	Spall or Back Side
Row	Sample No	Material	ORNL ID	Shot #	(J)	(ns)	(mm)	GW/cm^2	GPa	Damage?	Damage?
1	1-Tin side	Starphire	6by6by 3/4 thk	1	5.3	22.4	5.0	1.205	2.688	N	N
1	1-Tin side	Starphire	6by6by 3/4 thk	2	8.1	21.6	5.0	1.910	3.430	N	N
1	1-Tin side	Starphire	6by6by 3/4 thk	3	13.3	22.0	5.0	3.079	4.417	Υ	N
1	1-Tin side	Starphire	6by6by 3/4 thk	4	11.6	21.6	5.0	2.735	4.149	N	N
1	1-Tin side	Starphire	6by6by 3/4 thk	5	18.1	21.2	5.0	4.348	5.303	Υ	N
2	1-Tin side	Starphire	6by6by 3/4 thk	1	22.0	20.8	5.0	5.387	5.940	Υ	Υ
2	1-Tin side	Starphire	6by6by 3/4 thk	2	21.9	20.0	5.0	5.577	6.050	Υ	N
2	1-Tin side	Starphire	6by6by 3/4 thk	3	23.7	20.4	5.0	5.917	6.242	Υ	N
2	1-Tin side	Starphire	6by6by 3/4 thk	4	31.6	17.6	5.0	9.144	7.860	Υ	N




Borofloat Borosilicate Glass Air Side

										Visible	Visible	
					Energy	Pulse Width	pot Diamet	ower Densit	Pressure	Contact Side	Spall or Back Side	Comments
Row	Sample No	Material	ORNL ID	Shot#	(J)	(ns)	(mm)	GW/cm^2	GPa	Damage?	Damage?	
	12120100	_								1	122	
1	2-Air side	Borosilicate	6by6by 3/4 thk	1	5.0	20.8	5.0	1.224	2.711	N	N	
1	2-Air side	Borosilicate	6by6by 3/4 thk	2	8.0	21.6	5.0	1.886	3.408	N	N	
1	2-Air side	Borosilicate	6by6by 3/4 thk	3	8.0	21.2	5.0	1.922	3.442	N	N	
1	2-Air side	Borosilicate	6by6by 3/4 thk	4	13.7	21.2	5.0	3.291	4.576	Y (1 mm dia spot)	N	
2	2-Air side	Borosilicate	6by6by 3/4 thk	1	17.7	22.0	5.0	4.098	5.139	Y (7 mm dia)	N	
2	2-Air side	Borosilicate	6by6by 3/4 thk	2	21.7	20.4	5.0	5.418	5.957	Y (multiple)	N	
2	2-Air side	Borosilicate	6by6by 3/4 thk	3	23.7	20.0	5.0	6.035	6.308	Y (multiple)	N	
2	2-Air side	Borosilicate	6by6by 3/4 thk	4	31.4	18.8	5.0	8.506	7.565	Y Large Complex	N	
		Para 2712.6										
3	2-Air side	Borosilicate	6by6by 3/4 thk	0	34.2	18.0	5.0	9.677	8.099	Y Large Complex	N	
3	2-Air side	Borosilicate	6by6by 3/4 thk	1								
4	3-Air side	Borosilicate	Ch.,Ch., 2/4 4bl.	1	8.0	22.0	5.0	1.852	3.375	1	N	
1	3-Air side	Borosilicate	6by6by 3/4 thk		10.1	22.0	5.0	2.296	3.782	N N	N	
1			6by6by 3/4 thk	2					4.522	Y	N	
1	3-Air side	Borosilicate	6by6by 3/4 thk	3	13.9	22.0	5.0	3.218		Y	N	
1	3-Air side	Borosilicate	6by6by 3/4 thk	4	13.9	21.6	5.0	3.277	4.566	ļ Ÿ	N	
2	3-Air side	Borosilicate	Churchy 2/4 Abla	1	13.8	21.2	5.0	3.315	4.594	Y	N	
3			6by6by 3/4 thk								N	
3	3-Air side	Borosilicate	6by6by 3/4 thk	2	16.7	21.2	5.0	4.012	5.082	But center damage	N	Repeated shots at 10 new tape
3	3-Air side	Borosilicate	6by6by 3/4 thk	4	11.0	20.8	5.0	2.693	4.115	N	N	each hit
3	3-All side	Dorosilicate	obyoby 5/4 tilk	7	11.0	20.0	5.0	2.033	4.113	''	.,	Repeated shots at 10 new tape
3	3-Air side	Borosilicate	6by6by 3/4 thk	4	11.3	20.0	5.0	2.878	4.262	Y (1-2 mm)	N	each hit
										` ′		Repeated shots at 10 new tape
3	3-Air side	Borosilicate	6by6by 3/4 thk	4	10.6	21.6	5.0	2.499	3.955	Y (5-8 mm)	N	each hit
		_										Repeated shots at 10 new tape
3	3-Air side	Borosilicate	6by6by 3/4 thk	4	11.0	22.0	5.0	2.546	3.995			each hit




Borofloat Borosilicate Glass Tin Side

										VISIDIE	visible	
					Energy	Pulse Width	pot Diamet	ower Densi	Pressure	Contact Side	II or Back ₹	Comments
Row	Sample No	Material	ORNL ID	Shot#	(J)	(ns)	(mm)	GW/cm^2	GPa	Damage?	Damage?	
1	1-Tin side	Borosilicate	6by6by 3/4 thk	1	5.5	20.4	5.0	1.363	2.870	N	N	
1	1-Tin side	Borosilicate	6by6by 3/4 thk	2	7.7	22.0	5.0	1.783	3.307	Y (1 mm dia spot)	N	
1	1-Tin side	Borosilicate	6by6by 3/4 thk	3	14.1	22.0	5.0	3.264	4.556	Y	N	Well deveoped front damage zone
1	1-Tin side	Borosilicate	6by6by 3/4 thk	4	17.0	21.6	5.0	4.008	5.079	Y	N	Well deveoped front damage zone
2	1-Tin side	Borosilicate	6by6by 3/4 thk	1	22.1	20.4	5.0	5.517	6.015	Y	N	
2	1-Tin side	Borosilicate	6by6by 3/4 thk	2	23.6	20.8	5.0	5.779	6.164	Y	N	
												These shots cause preceding
												damaged regions to grow (see
2	1-Tin side	Borosilicate	6by6by 3/4 thk	3	32.4	17.0	5.0	9.707	8.112	Y	N	images)
2	1-Tin side	Borosilicate	6by6by 3/4 thk	4	34.2	17.6	5.0	9.897	8.196	Y	N	
3	1-Tin side	Borosilicate	6by6by 3/4 thk	0	33.8	18.2	5.0	9.438	7.992	Y	N	
	1 1 1 1 2 2 2 2 2	1 1-Tin side 1 1-Tin side 1 1-Tin side 1 1-Tin side 2 1-Tin side 3 1-Tin side	1 1-Tin side Borosilicate 1 1-Tin side Borosilicate 1 1-Tin side Borosilicate 1 1-Tin side Borosilicate 2 1-Tin side Borosilicate 2 1-Tin side Borosilicate 2 1-Tin side Borosilicate	1 1-Tin side Borosilicate 6by6by 3/4 thk 2 1-Tin side Borosilicate 6by6by 3/4 thk 3 1-Tin side Borosilicate 6by6by 3/4 thk 4 1-Tin side Borosilicate 6by6by 3/4 thk	1 1-Tin side Borosilicate 6by6by 3/4 thk 1 1 1-Tin side Borosilicate 6by6by 3/4 thk 2 1 1-Tin side Borosilicate 6by6by 3/4 thk 3 1 1-Tin side Borosilicate 6by6by 3/4 thk 4 2 1-Tin side Borosilicate 6by6by 3/4 thk 1 2 1-Tin side Borosilicate 6by6by 3/4 thk 2 2 1-Tin side Borosilicate 6by6by 3/4 thk 2 3 1-Tin side Borosilicate 6by6by 3/4 thk 3 4 1-Tin side Borosilicate 6by6by 3/4 thk 4	Row Sample No Material ORNL ID Shot # (J)	Now Sample No Material ORNL ID Shot # (I) (Ins)	Now Sample No Material ORN D Shot # (J) (ns) (mm)	No. Sample No Sample No Sample No 1-Tin side Borosilicate Borosilicate Subject Subject	Row Sample No Material ORNL ID Shot # (J) (ns) (mm) GW/cm²2 GPa 1	Nample No	Contact Side Ilor Back S Sample No Material 1-Tin side Borosilicate 6by6by 3/4 thk 1 1-Tin side Borosilicate 6by6by 3/4 thk 1 1-Tin side Borosilicate 6by6by 3/4 thk 2 7.7 22.0 5.0 1.783 3.307 1.783 1.




Fe-Containing Soda Lime Silicate Glass Air Side

										VISIBLE	VISIDIE
					Energy	Pulse Width	pot Diamet	ower Densi	Pressure	Contact Side	II or Back {Comments
Row	Sample No	Material	ORNL ID	Shot #	(J)	(ns)	(mm)	GW/cm^2	GPa	Damage?	Damage?
1	2 Air Side	Shelf Glass	6by6by 3/4 thk	1	5.0	21.6	5.0	1.167	2.643	N	N
1	2 Air Side	Shelf Glass	6by6by 3/4 thk	2	7.3	22.0	5.0	1.697	3.222	N	N
1	2 Air Side	Shelf Glass	6by6by 3/4 thk	3	13.4	22.0	5.0	3.102	4.435	Small spot	N
1	2 Air Side	Shelf Glass	6by6by 3/4 thk	4	11.2	21.6	5.0	2.641	4.072	N	N
1	2 Air Side	Shelf Glass	6by6by 3/4 thk	5	11.3	21.2	5.0	2.715	4.132	Small spot	N
3	2 Air Side	Shelf Glass	6by6by 3/4 thk	1	10.3	21.6	5.0	2.429	3.896	N	N
3	2 Air Side	Shelf Glass	6by6by 3/4 thk	2	13.6	21.6	5.0	3.207	4.513	N	N
3	2 Air Side	Shelf Glass	6by6by 3/4 thk	3	13.6	21.6	5.0	3.207	4.513	Y small	N
3	2 Air Side	Shelf Glass	6by6by 3/4 thk	4	16.4	21.2	5.0	3.940	5.033	N	N
4	2 Air Side	Shelf Glass	6by6by 3/4 thk	1	17.0	21.6	5.0	4.008	5.079	N	N
4	2 Air Side	Shelf Glass	6by6by 3/4 thk	2	21.5	20.4	5.0	5.368	5.928	Medium spot	N
4	2 Air Side	Shelf Glass	6by6by 3/4 thk	3	18.4	21.6	5.0	4.338	5.297	Medium small spo	t N
4	2 Air Side	Shelf Glass	6by6by 3/4 thk	4	18.7	20.4	5.0	4.669	5.506	Medium small spo	t N



Fe-Containing Soda Lime Silicate Glass Tin Side

					Energy	Pulse Width	pot Diamete	ower Densi	Pressure	Contact Side	II or Back (Comments
Row	Sample No	Material	ORNL ID	Shot #	(J)	(ns)	(mm)	GW/cm^2	GPa	Damage?	Damage?
1	1 Tin Side	Shelf Glass	6by6by 3/4 thk	1	4.9	22.4	5.0	1.110	2.573	N	N
1	1 Tin Side	Shelf Glass	6by6by 3/4 thk	2	8.1	21.6	5.0	1.915	3.435	multiple spots	N
1	1 Tin Side	Shelf Glass	6by6by 3/4 thk	3	12.9	22.0	5.0	2.986	4.346	multiple spots	N
1	1 Tin Side	Shelf Glass	6by6by 3/4 thk	4	16.9	21.2	5.0	4.060	5.114	Y	N
1	1 Tin Side	Shelf Glass	6by6by 3/4 thk	5	20.3	18.0	5.0	5.744	6.145	Y	N
3	1 Tin Side	Shelf Glass	6by6by 3/4 thk	1	21.3	20.4	5.0	5.318	5.899	medium spot	N
3	1 Tin Side	Shelf Glass	6by6by 3/4 thk	2	13.4	21.6	5.0	3.160	4.478	s outside of primar	/ plasma zone
3	1 Tin Side	Shelf Glass	6by6by 3/4 thk	3	7.9	21.2	5.0	1.898	3.419	N	N
3	1 Tin Side	Shelf Glass	6by6by 3/4 thk	4	7.6	21.2	5.0	1.826	3.350	spot on edge of las	€ N



ROBAX Glass Ceramic

										Visible	Visible	
					Energy	Pulse Width	pot Diamet	ower Densit	Pressure	Contact Side	Spall or Back Side	Comments
Row	Sample No	Material	ORNL ID	Shot #	(J)	(ns)	(mm)	GW/cm^2	GPa	Damage?	Damage?	
1	1	Robax	6by6by 1/4 thk	1	4.9	21.6	5.0	1.160	2.635	N	N	
1	1	Robax	6by6by 1/4 thk	2	7.6	22.8	5.0	1.698	3.223	N	N	
1	1	Robax	6by6by 1/4 thk	3	13.6	21.6	5.0	3.207	4.513	Y	Y Crack propagated to back surface	
3	1	Robax	6by6by 1/4 thk	1	8.7	22.0	5.0	2.021	3.535	Y	N	
3	1	Robax	6by6by 1/4 thk	2	10.3	21.2	5.0	2.462	3.924	Y	N	
3	1	Robax	6by6by 1/4 thk	3	12.0	21.2	5.0	2.871	4.257	Y	N	
3	1	Robax	6by6by 1/4 thk	0	11.6	21.2	5.0	2.787	4.190	Y	Y Crack propagated to back surface	
4	1	Robax	6by6by 1/4 thk	1	33.9	18.0	5.0	9.592	8.061	Y	Y Crack propagated to back surface; multiple large cracks	
1	2	Robax	6by6by 1/4 thk	1	7.9	21.2	5.0	1.898	3.419	l N	N	
1	2	Robax	6by6by 1/4 thk	2	8.9	21.2	5.0	2.138	3.642	N	N	
1	2	Robax	6by6by 1/4 thk	3	11.0	20.4	5.0	2.746	4.158	Yes Large	Y Crack propagated to back surface	
3	2	Robax	6by6by 1/4 thk	1	11.0	22.0	5.0	2.546	3.995	Yes Large	Y Crack propagated to back surface	
3	2	Robax	6by6by 1/4 thk	3	9.6	22.0	5.0	2.222	3.717	Medium	Y Crack propagated to back surface	

